

Intellitouch Pool and Spa Control Systems and Pump Temp Sensor



P/N: NSAB0103FC-612XSP7
Replacement part number :

Replaces Part Number: Pentair 520272,
TS5T,STS5T,520272,7790,R3002900,7784,7786,7791
Wide Application: Works as water, air or solar sensor.
20Feet Cable, 10k ohm Thermistor.Fits Zodiac Jandy
7790,Jandy Zodiac 7784, Pentair 520272

P/N: CWFB0103FC2-462XSP12b

Replacement part number:

Replaces Part No: GLX-PC-12-KIT,
AQ-SOL-LV, AQ-SOL-LV-TC, GL-30,
GL-235, GL-235 LV, GL-235LV/HV,
PC-10K,7790



P/N: CWFB0103FC2-612XSP12b

Fits with Zodiac Jandy 7790,
Jandy Zodiac 7784,
Pentair520272, AquaLink, GLX-
PC-12-Kit,TS5L



Intellitouch Pool and Spa Control Systems and Pump Temp Sensor



P/N: CWFB0103FC2-71I2B630 SUS
/CWFB0103FC2-71I6A630 Copper
42001-0053S

Material option :

- 1) Stainless Steel
- 2) Copper

P/N: CWFB0103FC2-352S15XSP
R0456500

Replace:

Jandy LRZE Heaters Jandy LRZM Heaters Jandy LXi Heaters Jandy JXi Heaters (Model 200, 260, 400), R0456500 Fits Zodiac Jandy Legacy LRZE, LRZM pool and spa heater models 125, 175, 250, 325, 400 Also fits Zodiac Jandy LXi Low NOx pool and spa heater models 250, 300, 400



P/N: CWFB1802JD8-650T2I

42002-0024S Fits Pentair MasterTemp pool and spa heater electrical systems Location: The Indoor Stack Flue Switch (ES2) / Stack Flue Sensor (SFS) is located on the exhaust Elbow.



P/N: CWF0103FC2-152T6C

Hayward IDXLTER1930
Fits Hayward H-Series Low Nox Heaters
Compatibility: H-Series Electronic ED2 Style, Low Nox Induced Draft Heaters, H250IDL2/H350IDL2/H400IDL2 Pool and Spa/Hot Tub Heaters, Electronic Ignition H150/H200/H210/H250/H300/H350/H400 Pool and Spa/Hot Tub Heaters

Intellitouch Pool and Spa Control Systems and Pump Temp Sensor



P/N: CWF-0103FC2-152T6C

471566, Fits Pentair MiniMax NT STD, NT LN, NT TSI pool and spa heater models 200, 250, 300, 400 Also fits UltraTemp and ThermalFlo pool and spa heatpumps

P/N: CWF0103FC2-152T6C

471566, Fits Pentair MiniMax NT STD, NT LN, NT TSI pool and spa heater models 200, 250, 300, 400 Also fits UltraTemp and ThermalFlo pool and spa heatpumps



P/N: CWFB0103FC2-152T2CSP

Hayward FDXLTER1930 Fits hayward universal h-series low nox pool heater models h150fdn, h150fdp, h200fdn, h200fdp, h250fdn, h250fdp, Also fits hayward universal h-series low nox pool heater models h300fdn, h300fdp, h350fdn, h350fdp, h400fdn, h400fdp





P/N: Pt102B-160-6D97L
Replacement part number :

12001566,WB2011X53,12001554,12500029,AP4009009,81896
79, 04000052, 04100258, 12001357, 12001554,12500029,
1364, 7-4657, 704657, 71003083,74003390, 74004471,
74004943, 74005193, 7430P003-60, 7430P005-60, 7430P008-
60, 7430P008-60K,7430P010-60, 7430P042-60, 879368,
AH1570174,EA1570174, PS1570174, W10127323,
Y04000052,Y04100258, Y704657

P/N: Pt102B-160-5D82L
Replacement part number:
12001655,AP4009456 04000051,
12001356, 12001555,12001655VP, 1365,
74002625, 74003094, 74003413,74004470,
74004944, 74005192, 7430P001-
60,7430P002-60, 7430P004-60, 7430P007-
60, 7430P007-60K, 7430P009-60,
7430P041-60, AH2003225,EA2003225,
PS2003225, W10127322, Y04000051



P/N: Pt102B-55-6D97L
Replacement part number:
Replaces part numbers:
W10131825,AP4321511,4455636,
1449853, AH2180067,
EA2180067,PS2180067.



Replace: WP9755542,MaxRed ME
10001 ,318601302,7318601302, 7318601300 0410,
73186013000410, AP4316140, 1380759,318601300,
AH2333343,EA2333343, PS2333343, 3051760217,
1250212894000, 1250236029005,
2924289060039,2924299060177, 3051760001,
3051760019,3051760118, 3251760009, 3259353609,
4002742007,50219878001, 6055176017, 6055556010,
6612594603,7632101007, 805006920005,
8996612352105,8996612594607, 948685003, 952446003,
955316005,959509076